		line 11, change "blades" to read - blades, the adhesion layers -;	
a		line 22 delete "comprised in"; and	
		line 29, delete "comprised therein".	
		Page 2, line 5, change the line to read - turbine, which parts are exposed to	
A	ν ⁵	hot gases, can be protected in that Ni powder, which is provided with a bonding	
		agent,;	
		line 6, delete "agent";	
		line 8, after "heat-treated." insert the following heading:	
		SUMMARY OF THE INVENTION;	
end Pedd Pedd	10	line 18, after "alitizing" insertor calorizing; and	
ii.		line 21, delete "comprised therein".	
2 22 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			
eric . est		Page 3, line 5, change "Hf or Ce can also be employed instead of Y." to read	
\overline{a}	3	instead of Y, Hf or Ce can also be employed	
	<u> </u>		
		Page 4, line 2, before "outer" insertan;	
	15	line 4, change "a drawing" to readthe drawings;	
		line 5, replace this line with the following heading:	
		BRIEF DESCRIPTION OF THE DRAWINGS;	
		line 6, after "1" insert - is a photomicrograph of-	
at		line 7, after "2" insert - is a photomicrograph of ;	
Uns	20	same line, after "alitizing." insert the following heading:	
11	,	DESCRIPTION OF THE PREFERRED EMBODIMENT -: and	
_a	?	line 18 after "formation of" insertthe	